

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**

FIG.1






FIG.2




APPLIED VOLTAGE 100V

FIG.3




APPLIED VOLTAGE 150V

FIG.4




APPLIED VOLTAGE 200V

FIG.5




APPLIED VOLTAGE 300V

FIG.6




APPLIED VOLTAGE 400V

FIG.7




APPLIED VOLTAGE 500V

FIG.8




APPLIED VOLTAGE 600V

FIG.9




APPLIED VOLTAGE 700V

FIG.10



APPLIED VOLTAGE 800V

FIG.11



APPLIED VOLTAGE 900V

FIG.12




APPLIED VOLTAGE 800V

FIG.13



APPLIED VOLTAGE 800V


FIG.14



APPLIED VOLTAGE 800V




FIG.15



APPLIED VOLTAGE 800V

FIG.16



APPLIED VOLTAGE 800V

FIG.17

PRIOR ART




FIG.18

PRIOR ART

